

X-O Rust Paint & Primer In one Gloss Aerosol



DESCRIPTION

Superior interior/exterior rust preventative gloss enamel paint and primer in one. Direct to metal, spray at any angle, comfort spray tip.

ENVIRONMENTAL STATEMENT

Contains no CFC's which deplete the ozone layer

COLORS

XOP-1 Gloss White
XOP-2 Gloss Black
XOP-7 Medium Green
XOP-8 Blue
XOP-10 Aluminum
XOP-11 Hunter Green
XOP-15 Machinery Gray
XOP-20 Seal Brown
XOP-23 Almond
XOP-25 Light Blue
XOP-26 Pebble
XOP-21 Bronze
XOP-39 Fiesta Red
XOP-40 Shutter Burgundy
XOP-41 Hot Red
XOP-44 Charleston Green



X-OP Rust Gloss

TYPE: Medium oil alkyd, interior/exterior Paint and Primer in One

VOC/MIR

VOC & MIR COMPLIANT

Maximum 65% VOC & 1.4 pw MIR for gloss enamels.

Maximum 80% VOC & 1.9 pw MIR for metallic

GLOSS AT 60°

Gloss Enamels: 80-90

PERCENT SOLIDS BY WEIGHT

XOP-1 Gloss White 22.86%

Product Features

- Superior rust protection
- Paint & Primer in one
- Direct to Metal
- Exceptional Durability
- Lasts Longer

FLASH POINT

< 20° F.

RECOMMENDED USE:

Rust-preventative coating for all interior and exterior metal surfaces. Also for wood, masonry and handcrafts. Do not use on Styrofoam, ceramic tiles or marble.

DRY TIME: Dry to touch 20 minutes. Tack free 3-4 hours. Recoat within one hour. High humidity or low temperature may increase dry time.

DISPOSAL: Dispose of aerosol container and unused contents in accordance with local, state and federal regulations. Do not burn, incinerate, puncture or place aerosol container in home garbage compactor.

CLEAN UP: Never stick sharp objects into the opening at the top of the can. For wet film, use mineral spirits. For dry film, use paint stripper, toluol or acetone.

DISPOSAL: To recycle or properly dispose of paint in your community, call 1-800-CLEANUP (USA only) or go to www.Earth911.org.

STORAGE: Do not store at temperatures above 120°F (50°C). Protect unused product from freezing.

APPLICATION METHODS

- Before spraying, shake can for 2 minutes after ball within begins to rattle and occasionally during use.
- Hold can 10" to 16" (25 to 40 cm) away from the surface and apply several thin coats a few minutes apart rather than one heavy coat, slightly overlapping each stroke.
- Keep can in motion while spraying. Recoat within one hour.

SURFACE PREP:

- Remove all grease, oil, dirt, wax and rust scale from surface.
- On new clean surface no primer is necessary. For rusty metal surfaces prime with X-O Rust Primer.
- New galvanized surfaces must weather 6 months before priming.
- Use with adequate ventilation.

WARNINGS

Contains propane, acetone and aromatic solvents. Extremely flammable. Storage and handling: Level-3 Aerosols.