

# Premium Décor High Heat



## DESCRIPTION

Superior interior/exterior high heat enamel spray at any angle, comfort spray tip. Takes heat up to 1000°F.

## ENVIRONMENTAL STATEMENT

Contains no CFC's which deplete the ozone layer



### Premium Décor High Heat

**TYPE:** Silicone Alkyd

**VOC/MIR**

VOC & MIR COMPLIANT

Maximum 80% VOC & 1.85 pw MIR for aluminum and 60% VOC & 1.2 pw MIR for Flat White & Flat Black

**GLOSS AT 60°**

White & Flat Black: 0-10

**PERCENT SOLIDS BY WEIGHT:**22.40%

PDS 1550

## COLORS

PDS-1550 Aluminum

PDS-1551 Flat White

PDS-1552 Flat Black

## Product Features

- Fast Drying
- Takes heat up to 1000° F
- Lasts Longer

## FLASH POINT

< 20° F.

## RECOMMENDED USE:

For interior or exterior surfaces such as barbecues, car engines, boilers, heaters, steam pipes and furnaces. Will not with-stand open flame. Do not use on Styrofoam, ceramic tiles or marble.

**DRY TIME:** Flat White & Black: Set to touch in 20-50 minutes. Tack free in 3-4 hours. Aluminum set to touch in 5-10 minutes. Tack free in 10-30 minutes. Recoat within one hour. High humidity or low temperature may increase dry time.

**DISPOSAL:** Dispose of aerosol container and unused contents in accordance with local, state and federal regulations. Do not burn, incinerate, puncture or place aerosol container in home garbage compactor.

**CLEAN UP:** Never stick sharp objects into the opening at the top of the can. For wet film, use mineral spirits. For dry film, use paint stripper, toluol or acetone.

**DISPOSAL:** To recycle or properly dispose of paint in your community, call 1-800-CLEANUP (USA only) or go to [www.Earth911.org](http://www.Earth911.org).

**STORAGE:** Do not store at temperatures above 120°F (50°C). Protect unused product from freezing.

## APPLICATION METHODS:

- Before spraying, shake can for two minutes after ball within begins to rattle Shake can occasionally during use
- Hold can 10" to 16" (25 to 40 cm) away from the surface
- For a smooth finish, spray in a sweeping motion
- To avoid runs and drips, apply several thin coats rather than one heavy coat

## Surface Prep:

- Remove all grease, oil, dirt, wax and rust scale from surface.
- On new, bare and rusty surfaces Premium Décor or XOP Primer is recommended.
- New galvanized surfaces must weather 6 months before priming.
- Use with adequate ventilation.

## WARNINGS

Contains propane, acetone, aromatic solvents and petroleum distillates. Extremely flammable. Storage and handling: Level-3 Aerosols.