



X-O Rust Paint & Primer In one Satin Aerosol

DESCRIPTION

Superior interior/exterior rust preventative satin enamel paint and primer in one. Direct to metal, spray at any angle, comfort spray tip.

ENVIRONMENTAL STATEMENT

Contains no CFC's which deplete the ozone layer



X-OP Rust Satin

TYPE: Medium oil alkyd, interior/exterior Paint and Primer in One

VOC/MIR

VOC & MIR COMPLIANT

Maximum 65% VOC & 1.4 pw MIR for satin enamels.

GLOSS AT 60°

Satin Enamels: 15 - 25

PERCENT SOLIDS BY WEIGHT 20.6%

XOP-31

COLORS

XOP-18 Satin Black

XOP-31 Satin White

XOP-45 Destination Bronze

FLASH POINT

< 20° F.

Product Features

- Superior rust protection
- Paint & Primer in one
- Direct to Metal
- Exceptional Durability
- Lasts Longer

RECOMMENDED USE:

Rust-preventative coating for all interior and exterior metal surfaces. Also for wood, masonry and handcrafts. Do not use on Styrofoam, ceramic tiles or marble.

DRY TIME: Dry to touch 20 minutes. Tack free 3-4 hours. Recoat within one hour. High humidity or low temperature may increase dry time.

DISPOSAL: Dispose of aerosol container and unused contents in accordance with local, state and federal regulations. Do not burn, incinerate, puncture or place aerosol container in home garbage compactor.

CLEAN UP: Never stick sharp objects into the opening at the top of the can. For wet film, use mineral spirits. For dry film, use paint stripper, toluol or acetone.

DISPOSAL: To recycle or properly dispose of paint in your community, call 1-800-CLEANUP (USA only) or go to www.Earth911.org.

STORAGE: Do not store at temperatures above 120°F (50°C). Protect unused product from freezing.

APPLICATION METHODS

- Before spraying, shake can for 2 minutes after ball within begins to rattle and occasionally during use.
- Hold can 10" to 16" (25 to 40 cm) away from the surface and apply several thin coats a few minutes apart rather than one heavy coat, slightly overlapping each stroke.
- Keep can in motion while spraying. Recoat within one hour.

SURFACE PREP:

- Remove all grease, oil, dirt, wax and rust scale from surface.
- On new clean surface no primer is necessary. For rusty metal surfaces prime with X-O Rust Primer.
- New galvanized surfaces must weather 6 months before priming.
- Use with adequate ventilation.

WARNINGS

Contains propane, acetone and aromatic solvents. Extremely flammable. Storage and handling: Level-3 Aerosols.