

# Woodsman Surface Prep



## DESCRIPTION

A wood brightener restores wood to its natural look. Removes mildew and algae stains, mill glaze.

### WDB FORMULA ANALYSIS

#### Sheen/Type Finish:

Weight per Gallon = 8.79 lbs.

Percent Solids by Weight = N/A

Percent Solids by volume = N/A

Viscosity Range = N/A

V.O.C. = Less than 4%

MPI Certification = N/A

- For decks, fences & siding
- Great for all wood types
- Fast acting – Results in 10 minutes
- Removes: Mildew & algae stains, black tannin stains & mill glaze
- Prepares surface for sealers & stains
- Use after stripping the deck for re-stain

**DRY TIME: 77°F @50% humidity:** Allow wood to dry thoroughly before applying water based finish and at least 24 hours before applying oil based finish

**Recoat: N/A**

**Coverage:** 250 – 300 Sq. Ft/Gal

**CLEAN-UP:** Rinse equipment and surface thoroughly with plenty of water.



## DESCRIPTION

A wood stripper removes all old finishes including weathered latex and oil based stains, toners and clear coatings to prepare the surface for stain.

### WDS FORMULA ANALYSIS

#### Sheen/Type Finish:

Weight per Gallon = 8.56 lbs.

Percent Solids by Weight = N/A

Percent Solids by volume = N/A

Viscosity Range = N/A

V.O.C. = Less than 4%

MPI Certification = N/A

- Removes solid & semi-transparent finishes
- For decks, fences & siding
- Great for all wood types
- Fast acting – Results in 15 minutes
- Great “first step” for preparing a previously stained deck for a re-stain

**DRY TIME: 77°F @50% humidity:** Allow wood to dry thoroughly before applying water based finish and at least 24 hours before applying oil based finish

**Recoat: N/A**

**Coverage:** 150 – 200 Sq. Ft/Gal

**CLEAN-UP:** Rinse equipment and surface thoroughly with plenty of water.